



Pos	Cant.	Pieza	€
3	5	Lensing screw	1,93
4	1	motor flange standard	20,09
5	1	Collet chuck	19,58
6	2	*Deep groove ball bearing	7,98
7	1	Supporting disc	4,61
8	1	Fuse ring	2,31
9	1	Lock disk	9,85
10	1	Locking cover	15,43
11	1	compression spring	3,46
12	1	*locking pin	7,29
14	1	PTC resistor with connector	6,02
15	1	Litz wire with flat plug	2,95
16	1	stator	27,76
17	2	Lensing screw	1,93
18	1	*PTC holder	2,95
19	1	air guide ring	5,51
20	1	*Magnetic ring	11,04
21	1	Ball bearing alignment disc	3,97
22	1	Pass disk	2,31
23	1	*Antivibration bearing	2,95
24	1	*Deep groove ball bearing	4,00
25	1	*Anchor	35,44
26	1	*Coal w. silicone damping (for allmilling motors)	6,81
27	1	*Coal w. silicone damping u.Abschaltung (for all milling motors)	8,62
28	2	*coal holder	5,51
29	1	slide switch	7,29
30	1	compression spring	3,46
31	1	Switch rod long	9,98
32	1	Electronic speedometer control 1050 FME-1 230V for power cable module	71,15
33	1	*AMB/Kress power cable module	24,97
34	1	*housing cup	9,85
35	1	*motor housing	18,93